

PRODUCT ALERT

Clinical Center Standardization Committee



RECALL

ALARIS® MEDLEY™ TUBING LOT# 306726 AND LOT# 306756
September 2003 (3)

ISSUE FOLLOW UP

The 'back check' valve found on the Alaris primary administration sets manufactured prior to July 2003 may be defective.

MMD has two lots (#306726 and #306756) manufactured prior to July 2003.



➡ MMD Management

1. MMD Warehouse and unreleased CHS tubing have been checked. Sets with lot #306726 or #306756 have been pulled.
2. CHS check of all CC CHS-stocked locations (such as pyxis) is in process. Sets with lot #306726 or #306756 will be pulled by **8:00 PM 09-19-2003.**
3. Pulled tubing is being replaced with new product.

➡ Staff Management

1. **After 8:00 PM 09-19-2003**, check non-CHS-stocked locations for tubing
2. Place tubing into soiled utility room for CHS pick-up.
3. Replace tubing with pyxis stock or order new stock using Visual Supply Catalog (Item ID #11089 Alaris IV Admin. Tubing #2126).

"Thank you for your cooperation and support."